

CABLINE®-CA PLUG

Part No. 20633

Assembly Manual

9	S22440	October 5, 2022	K.Baba	R.Takei	H.Ikari
8	S18410	June 29, 2018	M.Nakamura		Y.Shimada
7	S16129	March 4, 2016	Y.Sasa	T.Kurachi	J.Tateishi
6	S15089	February 26, 2015	K.Baba		E.Kawabe
Rev.	ECN	Date	Prepared by	Checked by	Approved by

## 1. Purpose :

This manual is to explain the soldering method / process of the CABLINE-CA PLUG with cable, and assembly of SHELL-A, PULL-BAR.

## 2. Applicable connector :

Name: CABLINE-CA PLUG

Parts No.:

Set P/N	CABLE ASS'Y	20633-#**T-0#S
Discrete P/N	HOUSING ASS'Y	20634-#**T-02
	SHELL-A	2764-0**1-###
	PULL-BAR	2766-0**1

## 3. Fixtures :

## 3.1 Components and Instruments used in the condition confirmation

## • Pulse heater

Name	P/N	Manufacturer
Reflow head	NA-66	Nippon Avionics Co., Ltd.
Pulse heat power supply	TCW-215	Nippon Avionics Co., Ltd.

## • Heater chip

	10P	12P	20P	30P	40P	50P	60P
Thickness	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>	0.5 <sup>0</sup> <sub>-0.05</sub>
Width	4.2 <sup>0</sup> <sub>-0.03</sub>	5.0 <sup>0</sup> <sub>-0.03</sub>	8.2 <sup>0</sup> <sub>-0.03</sub>	12.2 <sup>0</sup> <sub>-0.03</sub>	16.2 <sup>0</sup> <sub>-0.03</sub>	20.2 <sup>0</sup> <sub>-0.03</sub>	24.2 <sup>0</sup> <sub>-0.03</sub>

Unit: mm

## • Recommended solder bar


Resin-free solder made by Uchihashi Estec Co., Ltd. was used.

Positions		10P	12P	20P	30P	40P	50P	60P
Solder size	AWG#34,36	φ0.14	φ0.14	φ0.14	φ0.14	φ0.14	φ0.14	φ0.14
	AWG#40~#44	φ0.1	φ0.1	φ0.1	φ0.1	φ0.1	φ0.1	φ0.1
Length		4.0mm	4.8mm	8.0mm	12.0mm	16.0mm	20.0mm	24.0mm
		Ref.	Ref.	Ref.	Ref.	Ref.	Ref.	Ref.

Unit: mm

## 4. Recommended pulse heat condition

	SGC
① Idle temp.	150°C
② 1 <sup>st</sup> heat temp.	220°C
③ " rise time	0.5sec.
④ " holding time	3.0sec.
⑤ 2 <sup>nd</sup> heat temp.	300~320°C
⑥ " rise time	0.5sec.
⑦ " holding time	3.0sec.
Heater tip Pressure	5~10N



※ This pulse heat condition was evaluated and confirmed by our pulse heat jig and instruments.



The most optimum condition may change based on the shapes of pulse heat jig and instruments, the environments, or other reason.

Therefore, please examine the pulse heat condition adequately in advance of use.

## 5. Work procedures :

### 5-1. Soldering of center-conductor


① The cables have to be fabricated as shown below in advance of soldering.




### MICRO COAX CABLE DIMENSION

	a	b	c
#36	0.15	0.29	0.39
#38	0.12	0.285	0.39
#40	0.09	0.21	0.33
#42	0.075	0.20	0.28
#44	0.063	0.18	0.26

MICRO COAX CABLE #36 : POWER ONLY




RECOMMENDED DISCRETE CABLE DIM.




DISCRETE DIMENSION

	d	e
#34	0.192	0.32
#36	0.15	0.25

DISCRETE AWG#\*\*



RECOMMENDED TWINCOAX CABLE DIM.



TWINCOAX AWG#40

- ② Apply flux to contact by the dispenser etc., and please confirm all contacts were applied flux.

Applying Flux area





Photo.1 After applying flux

- ※ Please do not apply flux too much like Photo.2. It can cause flux splash or leak to the mating area.




Photo.2 Extra flux

- ※ Washer must not be used to take flux off because it may cause flux attached to mating area.

- ③ Pre-set and locate solder bar at center of connector (HSG ASS'Y).




Fig.1 Set of solder bar

- ④ Set the cable.

※ Setting discrete cable is to protect 0.2MAX. as Fig.3. There is danger that Center Conductor touch SHELL.




Fig.2 Set of cable




Fig.3 Setting Discrete Cable



Caution: The SHELL bottom side of PLUG HSG ASS'Y has convex shape at the points shown in Fig.4, so please make escape shape on the receiving jig of the pulse heater to prevent interference.

	A	B
10P	3.4	9.4
12P	4.1	10.2
20P	—	13.4
30P	4.0	17.4
40P	8.0	21.4
50P	12.0	25.4
60P	16.0	29.4

Confidential C

※When solder bridge is appeared between the terminal, try heating again with pulse heater only one time.

If the bridge isn't repaired, use the soldering iron only a NG point.

Condition of Soldering iron : 50W

Operating temperature : 350°C

Application time of soldering iron : Within 5sec.

※Because it might give product damage, please do not instigate a cable after soldering.

## 5-2. Cautions in treating SHELL-A

SHELL-A is delivered in the reel with a carrier. The following is the method to cut SHELL-A from Carrier.

- ① Cut carrier on the cut line of the left below picture (green line) by a scissors for metal.




Photo.4 Before cut




Photo.5 After cut

- ② Hold the center of Plug shell-A and cut it off from Notch by  $\pm 45^\circ$  of reciprocating work.  
When it does not be cut, try again this reciprocating work.  
After separated, check there is no burr around the cut part. (Photo.7)




Photo.6 Cut condition





Photo.7 After cut

## Plug SHELL-A (Detail of Notch)



Photo.8 Bottom side view




Photo.9 Upper side view

Caution: By pulling like the photo below to cut off by force (Red arrow direction), burrs and transformation can be caused.




Photo.10 Cut by force (Bad example)

## 5-3. Assembly of PULL-BAR

PULL-BAR is assembled to HOUSING ASS'Y.




Fig.5 Assembly of PULL-BAR

## 5-4. Assembly of SHELL-A

① SHELL-A is assembled from the upper side of HOUSING ASS'Y.




Fig.6 Assembly of SHELL-A

② Confirms whether SHELL-A is assembled properly.

Whether SHELL locks are assembled properly. (Fig.7 ★ point)




Fig.7 The assembly confirmation of SHELL-A



- ③ Soldering SHELL-A, B and GND BAR with the soldering iron at all designated points is recommended. (Fig.8,9 ◆ point)

Refer to Fig.12 for a limit of the solder height.

For conditions of Soldering iron refer to sheet 9.




Fig.8 Soldering of SHELL-A and GND BAR




Fig.9 Soldering of SHELL-B and GND BAR

- ④ Soldering SHELL-A and SHELL-B with the soldering iron at all designated points is recommended. (Fig.10 ◆ point)

Conditions of Soldering iron refer to sheet 9.




Fig.10 Soldering of SHELL-A and SHELL-B

## 5-5. Cable fixation

Fix the cable terminal part with the bond.

Bond : LOCTITE 352




Fig.11 Bonding




Fig.12 Soldering & Bonding