

# **NOVASTACK®4**

Part No.20641 , 20642


# Instruction Manual

7	S23193	August 21, 2023	W. Lau	Y. Baba	Y. Hashimoto
6	S17655	August 30, 2017	K. Tanaka	-	M. Takemoto
5	S17595	August 10, 2017	K. Tanaka	-	M. Takemoto
4	S17381	May 17, 2017	R. Hoshino	-	M. Takemoto
Rev.	ECN	Date	Prepared by	Checked by	Approved by
Confident	ial C		I-PEX Inc.		QKE-DFFDE09-03 REV.8

This manual provides the insertion & withdrawal methods and cautions to handle NOVASTACK® 4 connector properly.


- 1. Connector Name, Part number, Part name
- 1-1. Plug connector

Product Name: NOVASTACK 4 Plug Ass'y Part No.: 20641-0\*\*E



#### 1-2. Receptacle connector


Product Name: NOVASTACK 4 Receptacle Ass'y Part No.: 20642-0\*\*E



" \*\* " part shows the number of the connector position.

#### 1-3. Connectors Mating Direction

The ends of the connectors are not identical, but the plug and the receptacle can be mated in both ways. The performance of the connector will not be affected by the mating direction of the connectors. (Red line circle: end with dent Red dotted circle: end without dent)




#### 2. Mounting

2-1 The recommended pattern dimensions and the metal mask opening dimensions and thickness are shown in the product drawing.

#### 2-2 Reflow Temperature Profile

The thermal reflow temperature profile is shown in Graph 1. (The temperature mentioned refers to the surface temperature of the printed circuit board near the connector terminal.) Please refer to our product drawings for the recommended reflow temperature profile.




Graph 1 The Thermal Reflow Temperature Profile

2-3 Reflow conditions must be pretested before N2 reflow soldering.

#### 2-4 Hand Soldering


Do not apply flux when soldering by hands. The flux might rise inside the connector or it may scatter. The tip of the soldering iron must not touch the connector while soldering. A tip of the soldering iron shall touch the footprint pattern to prevent the connector from melting or deforming. Soldering iron tip temperature must be at 350  $^{\circ}C/3$  second when soldering.



#### 3. Cautions for Handling the Component


3-1. Using for board to FPC connection.

FPC shall not be tensed to withstand in case of a shock or a tension is applied. The FPC shall be fixed toward the mating direction for the maintenance.




$\sim$	nfide	- ntic	
1.0		-1112	11.
00	mav		

- 3-2. Using for board to board connection.
- ① To prevent the accidental removal or slant mating, spacers are recommended to fix the space in between the two printed circuit board. There spacers will also help to prevent the damage to the connectors and to the soldered area which might have been caused by the too large printed circuit board or unbalanced shape printed circuit board.




② Do not turn around the connector on the printed circuit board in case of using a screw. If the printed circuit boards were fixed in a wrong position, the connectors may get damaged.




#### 3-3. Press load

To prevent the coming off of the mated connectors (the load which a connector can apply), press the entire upper surface of the connector with the load calculated in below formula. (Maximum Press load : number of pin×1.2N or under)



#### 4. Mating and Un-mating


4-1. Always mate and un-mate the connectors horizontally. An excessive twisting or slanting when mating and un-mating will damage the connectors.



#### 4-2. Cautions


### [Caution 1]

Insertion angle shall not be slanted more than 10 degrees. Slanted degree over 10 degrees may cause the deformation of the connector.



# [Caution 2]


At starting the insertion, please keep the slant 10 ° or less in direction of depth. By inserting with the slant more than 10°, deformation of the connector will occur.



$\sim$	nfid.	ontial	
00	lillu	ential	


#### [Caution3]

Pressing straight from upper side, the posture becomes stable by guide function of connector. Do not insert forcedly from oblique direction.



#### [Caution4]

Do not mate or un-mate when the connector is turned around.



# 5. Others

5 -1. Solder-wicking may occur to the Hold down after mounting, but the performance of the connector will not be affected.

