

FPL II CONN. PLUG HOUSING ASS'Y

Part No. 20438-#**T-**

Packing Standard

8	S22142	March 31, 2022	T.Ono	T.Masunaga	H.Ikari
7	S21468	October 1, 2021	T.Onishi	T.Masunaga	H.Ikari
6	S14510	October 10, 2014	K.Tsusu		E.K
5	S13228	June 4, 2013	H.A		E.K
Rev.	ECN	Date	Prepared by	Checked by	Approved by

1. Product Name(s) and Parts Number(s)

Product Name(s): FPL II CONN. PLUG HOUSING ASS'Y

Parts Number(s): 20438-#**T-**

2. Packing Material

Pos.	TRAY P/N: 950268				SHIPPING CARTON	PACKING CARTON
	OUTER DIMENSION	POCKET WIDTH (REF. Fig2)	DEPTH	POCKET QTY.	P/N: 950001 OUTER DIMENSION	P/N: 950000 OUTER DIMENSION
30P	360x165	29.0x8.0	3.5	100 (Total)	385x175x90	406x406x214
40P						

Pos.	TRAY P/N: 950384				SHIPPING CARTON	PACKING CARTON
	OUTER DIMENSION	POCKET WIDTH (REF. Fig2)	DEPTH	POCKET QTY.	P/N: 950001 OUTER DIMENSION	P/N: 950000 OUTER DIMENSION
50P	360x165	37.0x8.0	3.5	75 (Total)	385x175x90	406x406x214

3. Packing Quantity

Pos.	QTY./ TRAY	QTY./ SHIPPING CARTON (TRAY QTY.)	QTY./ PACKING CARTON (S CARTON QTY.)
30P	100	2000 (20 TRAYS)	8000 (4 BOXES)
40P			
50P	75	1500 (20 TRAYS)	6000 (4 BOXES)

4. Label

The diagram shows a rectangular label with the following layout:

- Top Left:** Fields for P/N, QTY, and LOT.
- Top Right:** CHECK field with a stamp area (5).
- Bottom Left:** QR Code (5) and a 'RoHS Compliant' logo (9).
- Bottom Middle:** NAME field (4) and MADE IN ***** field (7).
- Bottom Right:** REMARK field.
- External:** A recycle mark (8) with '06 PS' and a 'HF' logo (10).

- ① Part Number
- ② Quantity
- ③ Ten Digits Product Lot Number

Y	Y	M	M	D	D	#	#	#	#
Year		Month		Day		Four Digit Code for I-PEX usage			

- ④ Product Name
- ⑤ QR Code
- ⑥ Check Stamp
- ⑦ Country of Origin
- ⑧ Recycle Mark and Compliance Mark
- ⑨ Logo Mark
- ⑩ Manufacture Name

5. Packing Method

Direction of products putting in tray.




Fig.1

[NOTE] Piling the tray to the same direction and putting a lid on the tray with empty tray.

※ Move metal shell upward, and pack it.




Fig.2

6. Packing Method




Fig.3

※ If operator pulls up the rubber band when they take out parts, there is possibility that tray bundle loosen and the parts drop out. Please note the taking up method.

