

MHF[®] series SMA Adapter for Plug and Receptacle

Packing Standard

8	S22504	November 22, 2022	Y. Imaji	K. Yufu	Y. Hashimoto
7	S22485	November 9, 2022	Y. Imaji	K. Yufu	Y. Hashimoto
6	S22464	October 21, 2022	Y. Imaji	K. Yufu	Y. Hashimoto
5	S22217	May 31, 2022	M. Toida	K. Yufu	Y. Hashimoto
Rev.	ECN	Date	Prepared by	Checked by	Approved by

1 . Product Name(s) and Part Number(s)

Items / Parts No.	High Cycle Adaptor
MHF I	90193-001, 90193-002, 90194-001, 90575-0001(*1), 90618-0001(*2), 90539-001(*3)
MHF II	90235-001, (*1), (*2), (*3)
MHF III	90285-001, 90285-002, 90286-001, 90491-001
MHF A	90413-001, 90413-002, 90527-001, 90684-0001(*4), 90416-001, 90539-001, (*1), (*2)
MHF 4	90449-001, 90449-002, 90449-003-0*, 90576-0001, 90638-0001, 90765-0001, 90720-0001, 90822-0001, 90683-0001, 90510-0001, 90698-0001, 90729-0001, (*2), (*4)
MHF 5	90543-0001, 90543-0002, 90586-000*, 90847-0001, 90690-0001, 90793-0001, (*2), (*4)
MHF 7S	91136-0001, 91145-0001, 91255-0001, 91256-0001
MHF-SW18	90709-0001, 90710-0001
MHF-SW20	90705-0001, 90706-0001
MHF-SW23	90604-0001, 90605-0001, 91183-0001

2. Packing Material

Tray	Packing Carton	
Dimension	Outer Dimension	Inner Dimension
315 x 245 x 30 mm	385 x 175 x 90 mm	370 x 280 x 180 mm

3. Packing Quantity

Pieces per Tray
100 pcs. MAX.

Product Quantity	Packing Carton Type
1 to 99 pcs.	Small carton
100 to 500 pcs.	Large carton

4. Label

P/N	①	CHECK	⑧ 托盘 03 PVC
QTY	②	⑥	
LOT	③		
	NAME:	REMARK	
	④ MADE IN ***** ← ⑦ ⑨	RoHS Compliant	
⑩			

- ① Part Number
- ② Quantity
- ③ Ten Digits Product Lot Number

Y	Y	M	M	D	D	#	#	#	#
Year		Month		Day		Four Digit Code for I-PEX usage			

- ④ Product Name
- ⑤ QR Code
- ⑥ Check Stamp
- ⑦ Counrty of Origin
- ⑧ Recycle Mark and Compliance Mark
- ⑨ Logo Mark
- ⑩ Manufacture Name

5. Packing Method

5-1 Product packing (into tray)

- (1) Put one product into one pocket.
- (2) Cut a tray for 1 to 99 pieces of samples as shown in figure 2.




Fig. 1 Tray

Cut the tray for small amount.




Fig. 2 Example of cutting tray

6. Packing Method




Fig. 3 99 pcs. or less






Fig. 4 100 pcs. or more

7. Label


Put labels on the carton surface where no logos nor other marks are printed.



If there is no space for some labels, put them inside the carton.

Fig. 5 Small carton

Seal Three Specified Areas with Transparent Packing Tape. (Top & Bottom)



Packing Carton

Put labels on the carton surface where no logos nor other marks are printed.

Fig. 6 Large carton